

1302 Madison Avenue  
Suite 200  
Dunmore, PA 18509



DEP LAB ID#: 35-04831

**Sekula Environmental Services**

605 Sterling Rd.  
Sterling, PA 18463


Chain of Custody Number	Sample Type	Project ID	Sample Date/Time	Accession Date
4840272	NPW	Walker Lake	08/12/2024 10:40 AM	08/12/2024

**Laboratory Information:**

Incubation: 8/12/24 16:42

Method	Test	Result	Unit	PQL	Analyst	Analysis Date/Time	Lab ID	Description
m-ColiBlue24	E. coli (Enumeration) (4)	<4	cfu/100mL	0	TC	08/13/2024 04:45 PM	8-24W31267	East Shore
m-ColiBlue24	E. coli (Enumeration) (4)	8	cfu/100mL	0	TC	08/13/2024 04:45 PM	8-24W31268	West Shore (E)

Date: 08/13/2024

Reviewed By:   
Michael J. Coyer, Ph.D., F-ABFT

1302 Madison Avenue  
Suite 200  
Dunmore, PA 18509




**DEP LAB ID#:** 35-04831

(E): (E) Results based upon colony counts outside the method's ideal range.

---

Date: 08/13/2024

Reviewed By:   

---

Michael J. Coyer, Ph.D., F-ABFT