

1302 Madison Avenue  
Suite 200  
Dunmore, PA 18509



**DEP LAB ID#:** 35-04831

**Sekula Environmental Services**

605 Sterling Rd.  
Sterling, PA 18463


Chain of Custody Number	Sample Type	Project ID	Sample Date/Time	Accession Date
1245606	NPW	Walker Lake	07/29/2024 10:50 AM	07/29/2024

**Laboratory Information:**

Incubation: 7/29/24 15:19

Method	Test	Result	Unit	PQL	Analyst	Analysis Date/Time	Lab ID	Description
m-ColiBlue24	E. coli (Enumeration) (4)	64	cfu/100mL	0	TC	07/30/2024 03:06 PM	7-24W30321	East Shore (E)
m-ColiBlue24	E. coli (Enumeration) (4)	<4	cfu/100mL	0	TC	07/30/2024 03:06 PM	7-24W30322	West Shore

Date: 07/30/2024

Reviewed By:   
Michael J. Coyer, Ph.D., F-ABFT

1302 Madison Avenue  
Suite 200  
Dunmore, PA 18509




**DEP LAB ID#:** 35-04831

(E): (E) Results based upon colony counts outside the method's ideal range.

---

Date: 07/30/2024

Reviewed By:   

---

Michael J. Coyer, Ph.D., F-ABFT