

1302 Madison Avenue  
Suite 200  
Dunmore, PA 18509



**DEP LAB ID#:** 35-04831

**Sekula Environmental Services**

605 Sterling Rd.  
Sterling, PA 18463


Chain of Custody Number	Sample Type	Project ID	Sample Date/Time	Accession Date
1404489	NPW	Walker Lake	06/03/2024 02:55 PM	06/03/2024

**Laboratory Information:**

Incubation: 6/3/24 17:36

Method	Test	Result	Unit	PQL	Analyst	Analysis Date/Time	Lab ID	Description
m-ColiBlue24	E. coli (Enumeration) (4)	4	cfu/100mL	0	TC	06/04/2024 05:21 PM	6-24W26893	East Shore (E)
m-ColiBlue24	E. coli (Enumeration) (4)	8	cfu/100mL	0	TC	06/04/2024 05:21 PM	6-24W26894	West Shore (E)

Date: 06/04/2024

Reviewed By:   
Michael J. Coyer, Ph.D., F-ABFT

1302 Madison Avenue  
Suite 200  
Dunmore, PA 18509




**DEP LAB ID#:** 35-04831

(E): (E) Results based upon colony counts outside the method's ideal range.

---

Date: 06/04/2024

Reviewed By:   

---

Michael J. Coyer, Ph.D., F-ABFT