

1302 Madison Avenue
Suite 200
Dunmore, PA 18509



DEP LAB ID#: 35-04831

Sekula Environmental Services

605 Sterling Rd.
Sterling, PA 18463


<u>Chain of Custody Number</u>	<u>Sample Type</u>	<u>Project ID</u>	<u>Sample Date/Time</u>	<u>Accession Date</u>
6381504	NPW	Walker Lake	05/22/2023 11:10 AM	05/22/2023

Laboratory Information:

Incubation: 5/22/23 16:01

<u>Method</u>	<u>Test</u>	<u>Result</u>	<u>Unit</u>	<u>PQL</u>	<u>Analyst</u>	<u>Analysis Date/Time</u>	<u>Lab ID</u>	<u>Description</u>
m-ColiBlue24	E. coli (Enumeration) (4)	<4	cfu/100mL	0	TC	05/23/2023 03:51 PM	5-23W11679	East Shore
m-ColiBlue24	E. coli (Enumeration) (4)	4	cfu/100mL	0	TC	05/23/2023 03:51 PM	5-23W11680	West Shore (E)

Date: 05/23/2023

Reviewed By: 
Michael J. Coyer, Ph.D., F-ABFT


1302 Madison Avenue
Suite 200
Dunmore, PA 18509



DEP LAB ID#: 35-04831

(E): (E) Results based upon colony counts outside the method's ideal range.

Date: 05/23/2023

Reviewed By: 

Michael J. Coyer, Ph.D., F-ABFT