

1302 Madison Avenue
Suite 200
Dunmore, PA 18509



DEP LAB ID#: 35-04831

Sekula Environmental Services

605 Sterling Rd.
Sterling, PA 18463


Chain of Custody Number	Sample Type	Project ID	Sample Date/Time	Accession Date
5265746	NPW	Walker Lake	08/14/2023 11:20 AM	08/14/2023

Laboratory Information:

Incubation: 8/14/23 16:31

Method	Test	Result	Unit	PQL	Analyst	Analysis Date/Time	Lab ID	Description
m-ColiBlue24	E. coli (Enumeration) (4)	12	cfu/100mL	0	TC	08/15/2023 04:31 PM	8-23W16561	East Shore (E)
m-ColiBlue24	E. coli (Enumeration) (4)	12	cfu/100mL	0	TC	08/15/2023 04:31 PM	8-23W16562	West Shore (E)

Date: 08/15/2023

Reviewed By: 
Michael J. Coyer, Ph.D., F-ABFT


1302 Madison Avenue
Suite 200
Dunmore, PA 18509



DEP LAB ID#: 35-04831

(E): (E) Results based upon colony counts outside the method's ideal range.

Date: 08/15/2023

Reviewed By: 

Michael J. Coyer, Ph.D., F-ABFT