

1302 Madison Avenue
Suite 200
Dunmore, PA 18509



DEP LAB ID#: 35-04831

Sekula Environmental Services

605 Sterling Rd.
Sterling, PA 18463

Chain of Custody Number	Sample Type	Project ID	Sample Date/Time	Accession Date
4271980	NPW	Walker Lake	06/05/2023 09:25 AM	06/05/2023

Laboratory Information:

Incubation: 6/5/23 16:09

Method	Test	Result	Unit	PQL	Analyst	Analysis Date/Time	Lab ID	Description
m-ColiBlue24	E. coli (Enumeration) (4)	4	cfu/100mL	0	TC	06/06/2023 04:13 PM	6-23W12262	East Shore (E)
m-ColiBlue24	E. coli (Enumeration) (4)	8	cfu/100mL	0	TC	06/06/2023 04:13 PM	6-23W12263	West Shore (E)

Date: 06/06/2023

Reviewed By:

A handwritten signature in black ink, appearing to read "Michael J. Coyer", is written over a horizontal line.

Michael J. Coyer, Ph.D., F-ABFT


1302 Madison Avenue
Suite 200
Dunmore, PA 18509



DEP LAB ID#: 35-04831

(E): (E) Results based upon colony counts outside the method's ideal range.

Date: 06/06/2023

Reviewed By: 

Michael J. Coyer, Ph.D., F-ABFT