

1302 Madison Avenue
Suite 200
Dunmore, PA 18509



DEP LAB ID#: 35-04831

Sekula Environmental Services

605 Sterling Rd.
Sterling, PA 18463


<u>Chain of Custody Number</u>	<u>Sample Type</u>	<u>Project ID</u>	<u>Sample Date/Time</u>	<u>Accession Date</u>
2075618	NPW	Walker Lake	07/18/2022 01:05 PM	07/18/2022

Laboratory Information:

Incubation: 7/18/22 16:59

<u>Method</u>	<u>Test</u>	<u>Result</u>	<u>Unit</u>	<u>PQL</u>	<u>Analyst</u>	<u>Analysis Date/Time</u>	<u>Lab ID</u>	<u>Description</u>
m-ColiBlue24	E. coli (Enumeration) (4)	12	cfu/100mL	0	TC	07/19/2022 04:51 PM	071822-040	East Shore
m-ColiBlue24	E. coli (Enumeration) (4)	>800	cfu/100mL	0	TC	07/19/2022 04:51 PM	071822-041	West Shore (E1)

Date: 07/21/2022

Reviewed By: 
Michael J. Coyer, Ph.D., F-ABFT

1302 Madison Avenue
Suite 200
Dunmore, PA 18509




DEP LAB ID#: 35-04831

(E): (E) Results based upon colony counts outside the method's ideal range.

(E1): (E1) TNTC or Too Numerous To Count indicates very high bacterial concentrations that hinder accurate colony counts.

Date: 07/21/2022

Reviewed By: 

Michael J. Coyer, Ph.D., F-ABFT