

1302 Madison Avenue
Suite 200
Dunmore, PA 18509



DEP LAB ID#: 35-04831

Sekula Environmental Services

605 Sterling Rd.
Sterling, PA 18463


Chain of Custody Number	Sample Type	Project ID	Sample Date/Time	Accession Date
3305543	NPW	Walker Lake	07/15/2024 10:15 AM	07/15/2024

Laboratory Information:

Incubation: 7/15/24 15:54

Method	Test	Result	Unit	PQL	Analyst	Analysis Date/Time	Lab ID	Description
m-ColiBlue24	E. coli (Enumeration) (4)	76	cfu/100mL	0	TC	07/16/2024 03:41 PM	7-24W29625	East Shore (E)
m-ColiBlue24	E. coli (Enumeration) (4)	104	cfu/100mL	0	TC	07/16/2024 03:42 PM	7-24W29626	West Shore

Date: 07/16/2024

Reviewed By: 
Michael J. Coyer, Ph.D., F-ABFT


1302 Madison Avenue
Suite 200
Dunmore, PA 18509



DEP LAB ID#: 35-04831

(E): (E) Results based upon colony counts outside the method's ideal range.

Date: 07/16/2024

Reviewed By: 

Michael J. Coyer, Ph.D., F-ABFT