

1302 Madison Avenue
Suite 200
Dunmore, PA 18509



DEP LAB ID#: 35-04831

Sekula Environmental Services

605 Sterling Rd.
Sterling, PA 18463


<u>Chain of Custody Number</u>	<u>Sample Type</u>	<u>Project ID</u>	<u>Sample Date/Time</u>	<u>Accession Date</u>
8847813	NPW	Walker Lake	06/13/2022 01:40 PM	06/13/2022

Laboratory Information:

Incubation: 6/13/22 17:30

<u>Method</u>	<u>Test</u>	<u>Result</u>	<u>Unit</u>	<u>PQL</u>	<u>Analyst</u>	<u>Analysis Date/Time</u>	<u>Lab ID</u>	<u>Description</u>
m-ColiBlue24	E. coli (Enumeration) (4)	<4	cfu/100mL	0	TC	06/14/2022 05:19 PM	061322-032	East Shore
m-ColiBlue24	E. coli (Enumeration) (4)	<4	cfu/100mL	0	TC	06/14/2022 05:19 PM	061322-033	West Shore

Date: 06/14/2022

Reviewed By: 
Michael J. Coyer, Ph.D., F-ABFT