

1302 Madison Avenue  
Suite 200  
Dunmore, PA 18509



DEP LAB ID#: 35-04831

**Sekula Environmental Services**

605 Sterling Rd.  
Sterling, PA 18463


<u>Chain of Custody Number</u>	<u>Sample Type</u>	<u>Project ID</u>	<u>Sample Date/Time</u>	<u>Accession Date</u>
4908221	NPW	Walker Lake	06/10/2024 03:35 PM	06/10/2024

**Laboratory Information:**

Incubation: 6/10/24 17:08

<u>Method</u>	<u>Test</u>	<u>Result</u>	<u>Unit</u>	<u>PQL</u>	<u>Analyst</u>	<u>Analysis Date/Time</u>	<u>Lab ID</u>	<u>Description</u>
m-ColiBlue24	E. coli (Enumeration) (4)	8	cfu/100mL	0	TC	06/11/2024 04:53 PM	6-24W27268	East Shore (E)
m-ColiBlue24	E. coli (Enumeration) (4)	48	cfu/100mL	0	TC	06/11/2024 04:54 PM	6-24W27269	West Shore (E)

Date: 06/11/2024

Reviewed By:   
Michael J. Coyer, Ph.D., F-ABFT

1302 Madison Avenue  
Suite 200  
Dunmore, PA 18509




**DEP LAB ID#:** 35-04831

(E): (E) Results based upon colony counts outside the method's ideal range.

---

Date: 06/11/2024

Reviewed By:   

---

Michael J. Coyer, Ph.D., F-ABFT