

1302 Madison Avenue
Suite 200
Dunmore, PA 18509



DEP LAB ID#: 35-04831

Sekula Environmental Services

605 Sterling Rd.
Sterling, PA 18463


<u>Chain of Custody Number</u>	<u>Sample Type</u>	<u>Project ID</u>	<u>Sample Date/Time</u>	<u>Accession Date</u>
1142313	NPW	Walker Lake	06/17/2024 04:25 PM	06/18/2024

Laboratory Information:

Incubation: 6/18/24 15:01

<u>Method</u>	<u>Test</u>	<u>Result</u>	<u>Unit</u>	<u>PQL</u>	<u>Analyst</u>	<u>Analysis Date/Time</u>	<u>Lab ID</u>	<u>Description</u>
m-ColiBlue24	E. coli (Enumeration) (4)	48	cfu/100mL	0	TC	06/19/2024 02:52 PM	6-24W27693	East Shore (E)
m-ColiBlue24	E. coli (Enumeration) (4)	12	cfu/100mL	0	TC	06/19/2024 02:52 PM	6-24W27694	West Shore (E)

Date: 06/19/2024

Reviewed By: 
Michael J. Coyer, Ph.D., F-ABFT


1302 Madison Avenue
Suite 200
Dunmore, PA 18509



DEP LAB ID#: 35-04831

(E): (E) Results based upon colony counts outside the method's ideal range.

Date: 06/19/2024

Reviewed By: 

Michael J. Coyer, Ph.D., F-ABFT