

1302 Madison Avenue
Suite 200
Dunmore, PA 18509



DEP LAB ID#: 35-04831

Sekula Environmental Services

605 Sterling Rd.
Sterling, PA 18463


<u>Chain of Custody Number</u>	<u>Sample Type</u>	<u>Project ID</u>	<u>Sample Date/Time</u>	<u>Accession Date</u>
9835856	NPW	Walker Lake	05/30/2022 01:25 PM	05/31/2022

Laboratory Information:

Incubation: 5/31/22 14:24

<u>Method</u>	<u>Test</u>	<u>Result</u>	<u>Unit</u>	<u>PQL</u>	<u>Analyst</u>	<u>Analysis Date/Time</u>	<u>Lab ID</u>	<u>Description</u>
m-ColiBlue24	E. coli (Enumeration) (4)	4	cfu/100mL	0	TC	06/01/2022 02:20 PM	053122-005	East Shore (E)
m-ColiBlue24	E. coli (Enumeration) (4)	20	cfu/100mL	0	TC	06/01/2022 02:20 PM	053122-006	West Shore (E)

Date: 06/02/2022

Reviewed By: 
Michael J. Coyer, Ph.D., F-ABFT


1302 Madison Avenue
Suite 200
Dunmore, PA 18509



DEP LAB ID#: 35-04831

(E): (E) Results based upon colony counts outside the method's ideal range.

Date: 06/02/2022

Reviewed By: 

Michael J. Coyer, Ph.D., F-ABFT