

1302 Madison Avenue
Suite 200
Dunmore, PA 18509



DEP LAB ID#: 35-04831

Sekula Environmental Services

605 Sterling Rd.
Sterling, PA 18463


Chain of Custody Number	Sample Type	Project ID	Sample Date/Time	Accession Date
4178684	NPW	Walker Lakes	08/22/2022 01:00 PM	08/22/2022

Laboratory Information:

Incubation: 8/22/22 17:33

Method	Test	Result	Unit	PQL	Analyst	Analysis Date/Time	Lab ID	Description
m-ColiBlue24	E. coli (Enumeration) (4)	8	cfu/100mL	0	TC	08/23/2022 05:19 PM	082222-075	East Shore (E)
m-ColiBlue24	E. coli (Enumeration) (4)	4	cfu/100mL	0	TC	08/23/2022 05:19 PM	082222-076	West Shore (E)

Date: 08/26/2022

Reviewed By: 
Michael J. Coyer, Ph.D., F-ABFT


1302 Madison Avenue
Suite 200
Dunmore, PA 18509



DEP LAB ID#: 35-04831

(E): (E) Results based upon colony counts outside the method's ideal range.

Date: 08/26/2022

Reviewed By: 

Michael J. Coyer, Ph.D., F-ABFT