

1302 Madison Avenue  
Suite 200  
Dunmore, PA 18509



**DEP LAB ID#:** 35-04831

**Sekula Environmental Services**

605 Sterling Rd.  
Sterling, PA 18463


Chain of Custody Number	Sample Type	Project ID	Sample Date/Time	Accession Date
4990124	NPW	Walker Lake	07/01/2024 10:35 AM	07/01/2024

**Laboratory Information:**

Incubation: 7/1/24 15:20

Method	Test	Result	Unit	PQL	Analyst	Analysis Date/Time	Lab ID	Description
m-ColiBlue24	E. coli (Enumeration) (4)	<4	cfu/100mL	0	TC	07/02/2024 03:31 PM	7-24W28591	East Shore
m-ColiBlue24	E. coli (Enumeration) (4)	<4	cfu/100mL	0	TC	07/02/2024 03:31 PM	7-24W28592	West Shore

Date: 07/02/2024

Reviewed By:   
Michael J. Coyer, Ph.D., F-ABFT